

DART AEROSPACE LTD	Work Order :	72581
	Description:	Inspection
	Approval :	<i>[Signature]</i>
		Page 1 of 1

Step	Location	Procedure	By	Date																												
1	PK	Remove from Stock Yes/No Return# <u>351</u>  <table border="1"> <thead> <tr> <th>Qty</th> <th>Part Number</th> <th>Description</th> <th>Batch</th> </tr> </thead> <tbody> <tr> <td><u>1</u></td> <td><u>D350-721-041</u></td> <td><u>Baslet</u></td> <td><u>B21899</u></td> </tr> <tr><td> </td><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td><td> </td></tr> </tbody> </table>	Qty	Part Number	Description	Batch	<u>1</u>	<u>D350-721-041</u>	<u>Baslet</u>	<u>B21899</u>																					<i>[Signature]</i>	05.03.01
Qty	Part Number	Description	Batch																													
<u>1</u>	<u>D350-721-041</u>	<u>Baslet</u>	<u>B21899</u>																													
2		Re-work/Inspection: (A) <u>Inspect Kit</u> (B) <u>Repack as per PPP D350-721-041</u> (C) <u>Shipping return to stock</u>	<i>[Signature]</i> <i>[Signature]</i> <i>[Signature]</i>	05.03.01 05/03/03 05/03/03																												
3	PK	Identify & Stock:  <table border="1"> <thead> <tr> <th>Qty</th> <th>Part Number</th> <th>Description</th> <th>Batch</th> </tr> </thead> <tbody> <tr><td> </td><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td><td> </td></tr> </tbody> </table>	Qty	Part Number	Description	Batch																										
Qty	Part Number	Description	Batch																													
		3.69	<i>[Signature]</i>	05-03-01																												
	PC	Close W/O Inspect Level 21	<i>[Signature]</i>	05.03.10																												

*[Signature]* 0503-10